

Please quote in reply 來函請註明

Letter No. 信件編號: BPV 21
Reference No. 檔案編號:
OP/99/00031 / PR/03/00095



Boilers & Pressure Vessels Division
Labour Department HKSARG
勞工處鍋爐及壓力容器科

Tel.No. / 電話號碼: 3107 3461

Fax No. / 傳真號碼: 25170875

Date / 日期: 18/05/2021

THE HONG KONG GOLF CLUB
DEEP WATER BAY LOT NO 1117,
DEEP WATER BAY, HONG KONG

The Owner,
擁有人:

Boilers and Pressure Vessels Ordinance, Cap. 56
香港法例第56章鍋爐及壓力容器條例

It has been brought to my attention that the registration number PR/03/00095 allotted to the registered equipment has not been engraved as advised in my previous letter.

本處早前曾發信提醒你，須在已登記的壓力器具上刻印獲編配的登記號碼PR/03/00095，但本處發現你沒有照辦。

You are advised to note that Section 16(2) of the Boilers and Pressure Vessels Ordinance stipulates that the registration number must be engraved, whether by impression or incision, in a conspicuous position on the equipment and be clearly legible at all times. Without the registration number engraved on the equipment, an Appointed Examiner would not be able to issue a Certificate of Fitness.

請注意，根據鍋爐及壓力容器條例第16(2)條的規定，登記號碼必須壓印或雕刻在有關壓力器的當眼地方，而在任何時間內，號碼都要清晰可辨。如壓力器上並沒有刻印登記號碼，委任檢驗師將無法簽發效能良好證明書。

As the registration number has not been marked in the above prescribed manner on your registered equipment, you are urged to have it engraved by a skilled workman on or before 17/06/2021. Failure to do so may result in legal liability if an accident occurred or legal proceedings being instituted against you.

你已登記的壓力器並沒有按上述指定方式刻印登記號碼。因此，現促請你在 2021 年 06 月 17 日或該日前，僱用技工將號碼刻印在有關壓力器上。如發生意外，你可能會因沒有按指示辦理而須負上法律責任，或本處可能會對你提出檢控。


Should you have any enquiries, please contact HON WAI LING at 3107 3458 .
如有任何查詢，歡迎致電 3107 3458 與 聯絡。

Yours faithfully,



(K L SHIU)
for Boilers and Pressure Vessels Authority
鍋爐及壓力容器監督
(蕭劍蘭 代行)

c.c. Appointed Examiner (WONG YUM WAH)
副本送: 委任檢驗師 (王欽華)



SHERMAN
1862

MADE IN GREAT BRITAIN
BY THE ROYAL ARTILLERY
REGIMENTAL CO. 101
LONDON

PR/03/00095